Firmware Release Notes

Araknis 210 Series Switches

Version 1.0.02

Release Details

Release Date	4/22/2016
Firmware Version	1.1.01
Product SKUs Affected	AN-210-SW-R-8 AN-210-SW-R-16 AN-210-SW-R-24

Resolved Functional/Local Issues

- Fixed issue where Trace Route would produce a cyclic page error with a warning showing “Unspecified error(Ox1EA)”.
- Fixed issue where the user was unable to disable Bandwidth Control without disabling all of QoS functionality in the switch.

Resolved Cloud Issues

- Fixed issue where link speed, duplex mode, or port naming could not be changed via OvrC.

Contacting Technical Support

Phone: (866) 838-5052

Email: support@araknisnetworks.com

© 2016 Araknis Networks®