



Product Name: VP-427x2

Current Version: Type

Туре	Number	Date
Firmware	V1.07	November 2021
Software	_	_
Web	1	_
Hardware	_	_

RN Date: November 29, 2021

Reference: 17783

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-427x2	Any	Yes	Yes

Summary:

- Bug fixes
- New firmware version

Codependency with Other Products and Software:

There is no codependency with other products or software.





Product Name: VP-427x2

Current Version: Type

Туре	Number	Date
Firmware	V1.07	November 2021
Software	_	_
Web	_	_
Hardware	_	_

RN Date: November 29, 2021

Reference: 17783

Bugs Fixed:

QC ID	Fixed Bug Description
79824	Typo in pop-up window.
79812	Icon shows that machine is ON after web login.
63846	Default UDP port 5000 does not listen to broadcast.

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: 1.05



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>





Product Name: VP-427x2

Current Version: Type

Туре	Number	Date
Firmware	1.05	June 2021
Software	_	_
Web	_	_
Hardware	_	_

RN Date: June 30, 2021

Reference: 008341

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
VP-427x2	N/A	N/A	N/A

Technical Notes:

• This is a release note for a new product.

Codependency with Other Products and Software:

• There is no codependency with other products or software.

KRAMER



Release Notes History



 $\label{eq:KRAMER ELECTRONICS, Ltd.} \textbf{KRAMER ELECTRONICS, Ltd.}$

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>





Product Name: VP-427X2

Current Version: Type

Туре	Number	Date
Firmware	1.05	June 2021
Software	_	_
Web	_	_
Hardware	_	_

RN Date: June 30, 2021

Reference: 008341

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/VP-427X2

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>